











2009-11-28: Niklas Kannenberg <kannenberg@quadrofly.com> 2009-11-28: Kolja Mieh] <mieh]@quadrofly.com> Quadrofly.com		
File: qf_mainboard.sch Sheet: /		
Title: QF Mainboard		
Size: A4	Date: 4 dec 2009	Rev: 1
KiCad E.D.A. EESchema (20090216-final)		Id: 1/7

7..14 V Input from Battery
expected output current noted

Main Power Supply

max 2 A

MCU, Onboard Headers



500 mA

Sensors, I2C Onboard Headers



max 1A

AD Reference (MCU ADC, EPOT)



max 1 mA

Optional Servo Supply
(Otherwise fed via Speed Control)

max 5 A



3..5 A

2009-11-20: Niklas Kannenberg <kannenberg@quadrofly.com> 2009-11-28: Kolja Mieh] <mieh]@quadrofly.com> Quadrofly.com		
File: pwr.sch		
Sheet: /PWR/		
Title: Power Supply		
Size: A4	Date: 4 dec 2009	Rev: 1
KiCad E.D.A. EESchema [200902216-final]		Id: 7/7


MCU PWR Supply
+5V
L5
100u
L3
10u
L4
10u
L5
10u
VCC
VCC1
VCC2
AVCC
C35
100n
C21
100n
C22
100n
C23
100n
C24
100n
C26
10u
XTAL2
X1
20 MHz
XTAL1
C36
18p
C37
18p
+3VAREF
C40
1u
C25
100n
AGND
R10
10k
/RESET
XTAL2
XTAL1
AREF
IC1
RESET
XTAL2
XTAL1
AREF
VCC2
VCC
VCC1
AVCC
GND1
GND
GND2
AGND
ATmega644-20AU
ADC7)PA7
ADC6)PA6
ADC5)PA5
ADC4)PA4
ADC3)PA3
ADC2)PA2
ADC1)PA1
ADC0)PA0
AXOUT
AYOUT
AZOUT
ZOUT-4x
XOUT-4x
YOUT-4x
AIRPRES
VBAT_ADC
acc
gyros
SCK)PB7
MISO)PB6
MOSI)PB5
SS)PB4
AIN1)PB3
AIN0)PB2
T1)PB1
T0)PB0
SLK
MISO
MOSI
PPM-01
PPM-02
PPM-03
PPM-04
PPM-05
PPM Outputs
TOSC2)PC7
TOSC1)PC6
PC5
PC4
PC3
PC2
PC1
PC0
PPM-06
PPM-07
/CS2
LED_RED
LED_GRN
SPI
JTAG
(NOT CONNECTED JTAG PINS)
nSRST
nTRST
TDI
TMS
TCK
TDO
1k
R13
1k
R14
100
R1
100
R2
SDA
SCL
I2C
OC2)PD7
ICP)PD6
OC1A)PD5
OC1B)PD4
INT1)PD3
INT0)PD2
TXD)PD1
RXD)PD0
/CS1
PPM-RX
PWM-02
PWM-01
TXD1
RXD1
TXD0
RXD0
SPI
PWM
UART
- C5 Leitungen
- 8. PPM Output
L7
100
AGND
2009-11-28: Niklas Kannenberg <kannenberg@quadrofly.com>
2009-11-28: Kolja Mieh] <mieh]@quadrofly.com>
Quadrofly.com
File: mcu.sch
Sheet: /MCU/
Title: MCU incl. External Wiring
Size: A4
Date: 4 dec 2009
Rev: 1
KiCad E.D.A. EESchema [200902]6-final]
Id: 3/7



2009-11-20: Niklas Kannenberg <kannenberg@quadrofly.com> 2009-11-28: Kolja Mieh] <mieh]@quadrofly.com> Quadrofly.com		
File: sensors.sch Sheet: /Sensors/		
Title: Sensors		
Size: A4	Date: 4 dec 2009	Rev: 1
KiCad E.D.A. EESchema [200902216-final]		Id: 6/7

pitch and roll gyros

X, Y



yaw gyro

Z



triple-axis accelerometer

X, Y, Z



IMU Connection



2009-11-28: Niklas Kannenberg <kannenberg@quadrofly.com>	
2009-11-28: Kolja Mieh] <mieh]@quadrofly.com>	
Quadrofly.com	
File: imu.sch	
Sheet: /IMU/	
Title: 6 DOF IMU	
Size: A4	Date: 4 dec 2009 — Rev: 1
KiCad E.D.A. EESchema [200902]6-final]	Id: 2/7

Battery Connector



Extension Plug

PB3, PB2, PD5, PD4



Was ist hiervon sinnvoll?

Bus Connections

ISP



AVR JTAG



SPI



I2C



Speed Control

UART





Sensors

optional

PPM I/O

PPM Input (Rx Signal)



PPM Outputs



Speed Control



CAM Servos



diodes are optional

2.54 mm pin headers

Avr Pin Convention:
Signals, 5 V, 3 V, GND

All connections are realized as On-Board Pin Headers in a row.

2009-11-28: Niklas Kannenberg <kannenberg@quadrofly.com>		
2009-11-28: Kolja Mieh] <mieh]@quadrofly.com>		
Quadrofly.com		
File: conn.sch		
Sheet: /CONN/		
Title: Connectivity		
Size: A4	Date: 4 dec 2009	Rev: 1
KiCad E.D.A. EESchema [200902]6-final]		Id: 5/7

Optional Power LEDs



Status Indication



Switching Outputs





2009-11-28: Niklas Kannenberg <kannenberg@quadrofly.com> 2009-11-28: Kolja Miehl <miehl@quadrofly.com> Quadrofly.com		
File: UI.sch		
Sheet: /UI/		
Title: User Interface		
Size: A4	Date: 4 dec 2009	Rev: 1
KiCad E.D.A. EESchema (2009-02-16-final)		Id: 4/7